



Bewdley North Signal Box seen from the roadway beneath it. The brickwork underneath the wooden superstructure bears witness to the modifications made in 1954, since when the upper portion was raised to increase the depth of the locking room, the inserted brickwork was of plain red brick, not patterned engineering brick. The signal box leans slightly towards the hill as a result of ground movement since its construction, this is unsurprising given the height of this earthwork.

[www.bewdleystation.co.uk](http://www.bewdleystation.co.uk)

Photograph By A.Coley