



A 10 ton capacity wagon, built for the Great Western Railway Engineering Department, newly outshopped from the Wagon Department. Repairs to the wagon fleet can be considerable, welding and riveting of steel plates can be conducted on site, as can the painting, woodworking and machining needed to keep these vehicles in good condition. The job is continuous, the van in the background being in line for remedial work. The white structure in the background was used to ensure that vehicles were within the loading gauge after being filled with their load.
Photograph By A.Coley